



MOTORCYCLE DOCTOR LLC

Craig Silvers,
Owner

PO Box 1676 / 108 N. Business Rt. 5 Camdenton, Mo 65020

local: (573) 346-6867 / toll free: (888) 346-6867

www.MOTORCYCLEDIATOR.com

craig@motorcycledoctor.com

Date:
08-17-2018

HiSun ECU (Engine) Harness UTV500-700

Ground Signal
from ECU to
Relay Fuel Pump


2013-18

**This Shows
Looking in at
Wire in End of
9 Pin Plug**

Warning
Temp.
Sensor

Reverse
Limit

Error
Code



Positive 12 Volts
'On all Time'

Positive 12 Volts
Key 'On'

Ground
Negative 12 Volts

RPM
Signal



= Green w/Blue Chaser



= Missing Pin Connector


Ground Signal
from ECU to
Relay Fuel Pump

2011-15

Ground to
Fuel Pump

Reverse
Limit

Error
Code



Positive 12 Volts
'On all Time'

Positive 12 Volts
Key 'On'
(Turns Red/White)

Ground
Negative 12 Volts

RPM
Signal