



# **MOTORCYCLE DOCTOR LLC**

**Craig Silvers,**  
Owner

PO Box 1676 / 108 N. Business Rt. 5 Camdenton, Mo 65020

Date:  
01-18-16

local: (573) 346-6867 fax: (573) 317-0011 toll free: (888) 346-6867

[www.MOTORCYCLEDOKTOR.com](http://www.MOTORCYCLEDOKTOR.com)

[craig@motorcycledoctor.com](mailto:craig@motorcycledoctor.com)

Here is your next update for your HiSun UTV.  
This will not allow water or dirt into the Differential, please  
apply to both Front and Rear.

This is found on  
the Hs1000 rear  
differential. This  
air tight flex boot  
should be added  
to ALL HiSun  
UTVs and ATVs,  
Front and Rear !

