



MOTORCYCLE DOCTOR LLC

**Craig Silvers,
Owner**

**PO Box 1676 / 108 N. Business Rt. 5 Camdenton, Mo 65020
local; (573) 346-6867 fax; (573) 317-0011 toll free; (888) 346-6867**

**Date:
01-13-16**

www.MotorcycleDoctor.com

Craig@MotorcycleDoctor.com

This is found on the Hs1000 rear differential. This air tight flex boot should be added to ALL HiSun UTVs and ATVs, Front and Rear !

