



MOTORCYCLE DOCTOR LLC

Craig Silvers,
Owner

PO Box 1676 / 108 N. Business Rt. 5 Camdenton, Mo 65020

local: (573) 346-6867 / toll free: (888) 346-6867

www.MOTORCYCLEDOKTOR.com


craig@motorcycledoctor.com

Date:
04-03-17

Cam Sprocket Weight Springs Too Soft

Low tension,
no pre-load

High tension,
high pre-load



Bad, decompression weights open at start, has full compression

Good, decompression weights stay closed at start.

Has low compression, makes easy starts.