

MOTORCYCLE DOCTOR LLC

Craig Silvers, Owner

PO Box 1676 / 108 N. Business Rt. 5 Camdenton, Mo 65020

local; (573) 346-6867 fax; (573) 317-0011 toll free; (888) 346-6867

www MATARCYCI FRACTAR com

crain@motorcycledoctor.com


Date:


03-01-2019

50mm Higher Oil Level









Now longer Dip Stick lowers oil level back to early year level. This is burning the Wet Shoe Clutch system.

Replace with shorter Dip Stick or cut to to shorter length. This will solve many issues.