



MOTORCYCLE DOCTOR LLC

Craig Silvers,
Owner

PO Box 1676 / 108 N. Business Rt. 5 Camdenton, Mo 65020


Date:
03-16-2018

local: (573) 346-6867 / toll free: (888) 346-6867

www.MOTORCYCLEDOCTOR.com

craig@motorcycledoctor.com

UTV500 Cylinder Body 12100-004-0000 Changed for 2015 and newer ?



New



Missing Side Rubber

Old



Tensioner Guide 14520-004-0000

Is also different, Old side pad is too wide.