

MOTORCYCLE DOCTOR LLC

Craig Silvers, **Owner**


11-14-14

local: (573) 346-6867 fax: (573) 317-0011 toll free: (888) 346-6867

www.MOTORCYCLEDOCTOR.com

craig@motorcycledoctor.com

Use 6mm x 40 bolts for the UTV500 and 700 (5mm or 6mm UTV400) in Secondary Clutch to spread the sheave plates for Easy Belt removal.



Do not over tighten and remove when belt is on.