



MOTORCYCLE DOCTOR LLC

**Craig Silvers,
Owner**

PO Box 1676 / 108 N. Business Rt. 5 Camdenton, Mo 65020


**Date:
11-14-14**

local; (573) 346-6867 fax; (573) 317-0011 toll free; (888) 346-6867

www.MOTORCYCLEDIATOR.com

craig@motorcycledoctor.com

Use 6mm x 40 bolts for the UTV500 and 700 (5mm UTV400) in Secondary Clutch to spread the sheave plates for Easy Belt removal.



Do not over tighten and remove when belt is on.